

# STANDARD PLAN RELEASE SUMMARY HIGHLIGHTS

## Physical Facilities Department

*The following summary highlights changes in the various standard plan documents since the last update that are of particular importance.*

No.	Item Description	Standard Plan Buildings Affected						Priority Level
		Palmyra Release 9	Kirtland Release 9	Nauvoo Release 9	Fayette Release 7	Heritage Release 11	Legacy Release 12	
1	<b>Fayette Rostrum Rail</b> height has been modified to provide greater modesty for those seated on the stand.	Not Affected	Not Affected	Not Affected	X	Not Affected	Not Affected	3
2	<b>Lightning Cable Connection</b> at steeple has been modified. Conductor will now not penetrate through steeple base, but have hard connection above and below floor of base, for more water tight detail.	X	X	X	X	X	X	2
3	<b>Acoustical Tile:</b> New AC tile has been selected that should provide greater economical yet durable products.	X	X	X	X	X	X	2
4	<b>Walk-off Mats</b> have been added to SMS and are now an Owner provided item. FM should be consulted before identifying quantity on SMS.	X	X	X	X	X	X	3
5	<b>Window Widths</b> have been changed back to 2'-8" wide at request of PMs to accommodate modular brick. Be sure and coordinate your openings with VMR supplied product.	X	X	X	Not Affected	X	X	2
6	<b>Fiberglass Steeples</b> are now available for bidding in addition to metal framed steeples.	X	X	X	X	X	X	3
7	<b>FHC Flag Signs</b> are now approved for stake centers with authorized Family History Centers.	Not Affected	Not Affected	X	Not Affected	Not Affected	X	3
8	<b>HVAC Sidewall Registers</b> in Chapel have been lowered at the direct request of the MSPM Directors.	X	X	X	Not Affected	X	X	3
9	<b>Palmyra Rostrum Rail</b> height has been modified to provide greater modesty for those seated on the stand. In order to accomplish extra height without adding weight the panel legs will come separate from the main panel.	Not Affected	Not Affected	Not Affected	X	Not Affected	Not Affected	3
10	<b>Palmyra Rostrum Ramp Sidewall:</b> Default is now a fixed hardwood panel system. The SS railing has been deleted.	X	Not Affected	Not Affected	Not Affected	Not Affected	Not Affected	2
11	<b>Recessed Projection Screen</b> details have been added to an option sheet for buildings that qualify for satellite, which are not stake centers.	Not Affected	X	Not Affected	Not Affected	X	Not Affected	3
12	<b>Removable Pulpit Step</b> has been added to all Chapel pulpits provided by Fieldcrest.	Not Affected	X	X	Not Affected	X	X	3